

MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY

BREATH ALCOHOL PROGRAM

DATAMASTER MAINTENANCE REPORT

REPORT /6

Complete this report at the time of the regular monthly preventive maintenance check (not to expenditure). Complete this report whenever the instrument is serviced or repaired and whenever it is placed. By Carol Day at 1:56 pm, Nov 08, 2013 Retain the original and send a copy within 15 days to the Breath Alcohol Program, DHSS.							
• •				DATE OF INSPECTION 11/07/2013			
LOCATION OF INSTRUMENT (STREET AND CITY)			TIME OF INSPECTION 16:03				
2920 North Shamrock Road, Jefferson City CHECKLIST: Place a mark in the box by each item if found to be satisfactory or if operating							
where determined.) Unmarked items must be corrected before using instrument.							
DIAGNOSTIC CHECK (PRINTOUT	ATTACHED)	DATE AND TIME	(from printout)	11/07/201	3 @ 16:03		
			· · · · · · · · · · · · · · · · · · ·				
✓ PROGRAM		FILTERS					
✓ HEATERS SAMPLE CHAMBER	+49°C	QUARTZ STAI	NDARD				
FLOW DETECTOR							
✓ PUMP HIGH SPEED	,	✓ PRINTER					
✓ INDICATOR LIGHTS							
SIMULATOR SOLUTION SUPPLIES	Guth Laboratories	LOT#_	13280 [EXP. DATE	10/16/2015		
SIMULATOR TEMP (34°C ± 0.2°C)	+34.00°C	SIMULATOR SN	DR5375	EXP. DATE	04/15/20	14	
✓ CALIBRATION CHECK - (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT)							
Run three tests using a standard solution. All three tests must be within ±5% of the standard value and must have a spread of .005 or less. Mark the box corresponding to the standard solution being used. (PRINTOUT ATTACHED)							
☐ 0.100% STANDARD - MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE ☐ 0.080% STANDARD - MUST READ BETWEEN 0.076% AND 0.084% INCLUSIVE ☐ 0.040% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE							
TEST 1098	TEST 2 🕶	.099	TEST 3099				
PERFORM R.F.I. TEST (PRINTOUT	ATTACHED)						
INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT: (DO NOT INCLUDE SELF-ADMINISTERED TESTS)							
REFUSALS 0 (004) 0	(.0509) 0	(.1014) 0	(.1519)	0 0	/ER.19 0		
LIST ANY NEW PARTS AND DESCRIBE ANY ALTERATION OR MODIFICATION THAT WAS MADE TO RESTORE THE INSTRUMENT TO OPERATE SATISFACTORILY AND WITHIN ESTABLISHED LIMITS (USE OTHER SIDE IF NECESSARY). Removed compacted fibers from breath tube mouthpiece receptacle. Replaced tubing between flow thermistor block and five-way valve. Blew sample chamber with compressed air. Replaced printer ribbon.							
INSPECTING OFFICER SIGNATURE PRINT FULL NAME							
· favorene 4	· (areus						
14PE II PERMIT NUMBERI EXPITATION DATE 230101	05/28/2015		751-4722				
RETURN COMPLETED REPORT TO THE: Breath Alcohol Program, MO Department of Health and Senior Services, Southeast District Office 2875 James Blvd. Poplar Bluff, MO 63901						Office	



CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 13280 of Alcohol Reference Solution for Simulator were analyzed by gas chromatography on October 18, 2013, using a Perkin Elmer Gas Chromatograph Autosystem XL S/N: 610N9030209, and found to contain 0.1217% (w/vol) ethyl alcohol. The expiration date for this lot number is October 16, 2015 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcohol analysis instrument reading of 0.100 g/210L +/- 3%.

The alcohol and water used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC.

NIST Traceability:

Testing was conducted using Cerilliant Reference Standard lot number FN122211-02 whose values are traceable to NIST.

All balances are calibrated annually by an outside agency using NIST traceable weights. Calibration verification is done prior to each use utilizing NIST traceable weights.

BAC DataMaster Evidence Ticket

MISSOURI STATE HIGHWAY PATROL

DIAGNOSTIC CHECK PROGRAM (04-07-2009): SAMPLE CHAMBER HIGH SPEEDS COMPUTER: DETECTOR: FILTERS: "##%%'()*+,-./0123456789:;<=>?@GBCDEFG

FACE THIS SIDE DOWN - THIS EDGE IN FIRST

CALIBRATION:

BAC DataMaster

OPERATOR SIGNATURE

Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204172 11/07/13

ARREST TIME: 00:00 SUBJECT NAME: Х DOB: 01/01/01 SEX: M STATE/D.L.: XX/X ARRESTING OFFICER: Х OFFICER I.D.: X TESTING OFFICER: CARVER/DEWAYNE/D OFFICER I.D.: C41 PERMIT NUMBER: 230101 EXPIRATION DATE: 05/28/15 MISCELLANEOUS DATA:

RFI TEST

--- BREATH ANALYSIS ---

BLANK TEST .000 16:10 [INTERNAL STANDARD VERIFIED 16:10 SUBJECT SAMPLE .000 16:19 RADIO INTERFERENCE

FACE THIS SIDE DOWN - THIS EDGE IN FIRST

BAC DataMaster

Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204172 11/07/13

TESTING OFFICER: CARVER/DEWAYNE/D OFFICER I.D.: C41 PERMIT NUMBER: 230101 EXPIRATION DATE: 05/28/15 MISCELLANEOUS DATA: .100 VAPOR ACCURACY CHECK GUTH LABS LOT 13280 EXP 10/16/2015

SUPERVISOR MODE ---

BLANK TEST	000	i6:05
INTERNAL STANDARD	VERIFIED	16:05
EXTERNAL STANDARD	.098	16:06
BLANK TEST	000	16:06
EXTERNAL STANDARD	.099	16:07
BLANK TEST	.000	16:07
EXTERNAL STANDARD	.099	16:08
BLANK TEST	.000	16:08
· · ·		

SIM. = .1 AVG. = .0986



STATE OF MISSOURI

DEPARTMENT OF HEALTH AND SENIOR SERVICES BREATH ALCOHOL PROGRAM



DEWAYNE D CARVER

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field service and repairs,

and operate the following breath analyzer(s): ALCO-SENSOR IV W/PRINTER, DATAMASTER, INTOX DMT

for the determination of the alcoholic content of blood from a sample of expired air. Permit issued under the provisions of sections 577.020 through 577.041, RSMo and 306.111 through 306.119 RSMo.

05/28/2015 05/28/2013 230101 MO 580-0771 (6-10) NUMBER EXPIRES _ DATE

Gal Vistel

DIRECTOR OF STATE PUBLIC HEALTH LABORATORY

An and

Acting Director

DIRECTOR OF DEPARTMENT OF HEALTH AND SENIOR SERVICES

LAB-4 (R6-10)